



Firmware Version: 3.10rc066
Published Date: 2010/09/23

Content:

Upgrading Instructions:..... 2

 Upgrading by using Web-UI..... 2

New Features:..... 2

Changes of MIB & D-View Module:..... 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:


Firmware Version	Date	Model	Hardware Version
3.10rc066	2010/09/23	DAP-1353	B1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.
To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

1. Add AP Repeater Mode function
2. Add AP Array function

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V3.10	<ol style="list-style-type: none"> 1. The time interval of wireless setting which does not have default value. 2. Time Zone should not support "copy computer time" 3. When set APR+ Use APC's Cloned MAC to send beacon will cause Root AP deauth APR forever. 4. When set APR connect with root AP, root AP will deauth APR continually

Known Issues:

Firmware Version	Known Issues
V3.10	None

Related Documentation:

- DAP-2553 User Manual v3.10