



Firmware Version: 3.15rc012
Published Date: 2011/05/19

Content:

Upgrading Instructions:..... 2

 Upgrading by using Web-UI..... 2

New Features:..... 2

Changes of MIB & D-View Module:..... 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:


Firmware Version	Date	Model	Hardware Version
3.15rc012	2011/05/19	DAP-1353	B1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.
To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

1. Support AP Array Setup tool
2. Support APMII v2.15 SNMP enable function
3. Upload/Download ACL file

Changes of MIB & D-View Module:

1. AP Manager II: v3.15
2. D-View: v3.15

Problems Fixed:

Firmware Version	Problems Fixed
V3.15	<ol style="list-style-type: none"> 1. Fix 20 clients issue 2. Hide the password when login from CLI & web security

Known Issues:

Firmware Version	Known Issues
V3.15	None

Related Documentation:

None