

## G416/CP Firmware Release Notes

**Date:** November 27<sup>th</sup>, 2023

---

**Release Image Filename:** G416A2\_FW107B24CP.bin

**MD5:** f4fe27e4fcf739c054196654eb485dbe

**Firmware Version:** V1.07.24CP

**Module Firmware Version:** 16121.1000.00.01.01.45

**Display Firmware Version:** V1.07.24CP

**Hardware Version:** A2

---

### Fixed Bugs:

1. 10663 WiFi password requirements not fulfilled
2. 10662 It is not possible to login after LAN settings change
3. 10666 Translation - APN Name text field
4. 10664 Translation [PL] - Wrong WiFi password set information
5. 10665 Overlapping text in connected clients view
6. Module FW upgrade implementation.

Test version:

G416A2\_FW198B23CP.bin [Module FW V44]

G416A2\_FW199B24CP.bin [Module FW V45 for FOTA]

### Known issues:

=====END=====